



福建联合石油化工有限公司
Fujian Refining & Petrochemical Company Limited

福建联合石化公司火炬排放情况说明

Information about the flare emission situation of FREP

2020年4月23日上午10时25分，我公司生产运行波动，导致火炬异常排放、火焰及黑烟。我公司已立即启动应急措施，排查故障并紧急抢修，以尽快恢复正常生产。

At 10:25 a.m. on April 23th 2020, our company's had an operational disturbance, which caused abnormal flaring, emitting black smoke and flame. Our company has started emergency response measures immediately for troubleshooting and emergent repair in order to resume normal operation as soon as possible.

福建联合石油化工有限公司

Fujian Refining & Petrochemical Company Limited

2020年4月23日

April 23th, 2020
